Firmware Update - OPTIBAR DP 7060 C / OPTIBAR Px 5060 C

The following components are required for the sensor update:
- Sensor
- Voltage supply
- USB Communicator Interface
- PC with PACTware
- OPTIBAR 5060 / 7060 DTM installed
- Actual sensor software as a file

To download PACTware, USB-Driver or DTMs please visit:
http://krohne.com/en/dlc/product-related-downloads/pressure-instruments/

Perform the following steps to update the sensor software:
- Connect the sensor to power supply and provide connection from the PC to the instrument via the interface adapter.
- Open PACTware software
- In the upper left corner right click on *"HOST PC"* and select *"Add Device"*.

- Choose "*USB-Communicator*" from the list.

Right click on "*USB*" and select "*Add Device*".

- Select the respective device from the list.

- A new tag named "*Sensor"* will appear on the left side. Open the submenu with right click on the tag "Sensor" and select the item "*connect*", to open the connection to the sensor.

- Open the submenu again, go to "Additional functions" and select the item "*software update*". PACTware checks the sensor data now and shows the actual hardware and software version of the sensor. This procedure takes approximately 60 seconds.

- Click the button "Next" and push the new appeared button "Selection". Go to the folder where the new firmware file is located and select the additional xml-file. PACTware checks the new firmware for compatibility.

- Push the button "Finish" to perform the update. Dependent on the sensor, this procedure takes up to 15 minutes.

File	Selection
File name: C:\Users\depaetkm\Desktop\Neuer Ordner\OPTIBAR-DP-7060C_HART_1_3_0.xml	

File information:

Instrument series	OPTIBAR DP 7060C HART
Software version	1.3.0/7

✓ The software update can be executed with the selected file.

< Back   Cancel   Finish

- Finally the following message is displayed: "Software update successfully executed".

Revision	Date	Comment
1.0	03.01.2017	Document created